




Aeroflex (MACOM Technology Solutions)

MACP-010562-TR1000

Varenummer:	MACP-010562-TR1000
Producent / Mærke:	Aeroflex (MACOM Technology Solutions)
Produkt beskrivelse:	RF DIR COUPLER 6GHZ-18GHZ 6TDFN
Dataark:	
RoHS Status:	Blyfri / RoHS-kompatibel
Lager tilstand:	3016 pcs stock
Skib fra:	Hong Kong
Forsendelsesmåde:	DHL/Fedex/TNT/UPS/EMS

ANMODNING OM TILBUD

Solutions



Billede kan være repræsentation. Se specifikationer for produkt detaljer.

Specifikationer for MACP-010562-TR1000

VARENUMMER	MACP-010562-TR1000
FABRIKANT	Aeroflex (MACOM Technology Solutions)
BESKRIVELSE	RF DIR COUPLER 6GHZ-18GHZ 6TDFN
BLYFRI STATUS / ROHS STATUS	Blyfri / RoHS-kompatibel
M/ENGDE TILG/ENGELIG	3016 pcs
DATABLAD	
LEVERANDØR DEVICE PACKAGE	6-TDFN (1.5x1.2)
SERIE	-
RETUR TAB	-20dB
STRØM - MAX	-
EMBALLAGE	Tape & Reel (TR)
PAKKE / TILFÆLDE	6-WDFDN Exposed Pad
ANDRE NAVNE	1465-1323-2
FUGTFØLSOMHEDSNIVEAU (MSL)	1 (Unlimited)
BLYFRI STATUS / ROHS STATUS	Lead free / RoHS Compliant
ISOLATION	-
INDSÆTNINGS TAB	0.3dB
FREKVENNS	6GHz ~ 18GHz
DETALJERET BESKRIVELSE	RF Directional Coupler 6GHz ~ 18GHz 6-WDFDN Exposed Pad
KOBLINGSFAKTOR	-
COUPLER TYPE	Standard
APPLIKATIONER	-

Relaterede tags

Aeroflex (MACOM Technology Solutions) MACP-010562-TR1000	MACP-010562-TR1000 Distributør	MACP-010562-TR1000 Leverandør
MACP-010562-TR1000 pris	MACP-010562-TR1000 Billeder	MACP-010562-TR1000 Image
MACP-010562-TR1000 PDF Datablad	MACP-010562-TR1000 Download datablad	MACP-010562-TR1000 datablad
MACP-010562-TR1000 lager	Køb MACP-010562-TR1000	Køb Aeroflex (MACOM Technology Solutions) MACP-010562-TR1000
Aeroflex (MACOM Technology Solutions) MACP-010562-TR1000	Aeroflex (MACOM Technology Solutions) Leverandør	Aeroflex (MACOM Technology Solutions) Distributør
Aeroflex (MACOM Technology Solutions) MACP-010562-TR1000	Aeroflex Circuit Technology MACP-010562-TR1000	Aeroflex MACP-010562-TR1000
Aeroflex (MACOM Technology Solutions) MACP-010562-TR1000	Aeroflex Metelics, Division of MACOM MACP-010562-TR1000	M/A-Com Technology Solutions MACP-010562-TR1000
Metelics (MACOM Technology Solutions) MACP-010562-TR1000	MACOM Technology Solutions MACP-010562-TR1000	

Relaterede produkter

<p>MACP-010563-TR1000 producenter: Aeroflex (MACOM Technology Solutions) Beskrivelse: RF DIR COUPLER 10GHZ-30GHZ 6TDFN På lager: 4446 pcs RFQ</p>	<p>MACP-010561-TR1000 producenter: Aeroflex (MACOM Technology Solutions) Beskrivelse: RF DIR COUPLER 2GHZ-6GHZ 6DFN På lager: 4662 pcs RFQ</p>
<p>MACP-011013 producenter: Aeroflex (MACOM Technology Solutions) Beskrivelse: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD På lager: 75305 pcs RFQ</p>	<p>MACP-010563-001SMB producenter: Aeroflex (MACOM Technology Solutions) Beskrivelse: EVAL BOARD FOR MACP-010563-TR100 På lager: 4608 pcs RFQ</p>
<p>MACP-010562-000000 producenter: Aeroflex (MACOM Technology Solutions) Beskrivelse: RF DIR COUPLER 6GHZ-18GHZ 6TDFN På lager: 4595 pcs RFQ</p>	<p>MACP-010561-001SMB producenter: Aeroflex (MACOM Technology Solutions) Beskrivelse: EVAL BOARD FOR MACP-010561-TR100 På lager: 3678 pcs RFQ</p>
<p>MACP-010562-001SMB producenter: Aeroflex (MACOM Technology Solutions) Beskrivelse: EVAL BOARD FOR MACP-010562-TR100 På lager: 5017 pcs RFQ</p>	<p>MACP-010507-CH0160 producenter: Aeroflex (MACOM Technology Solutions) Beskrivelse: RF DIR COUPLER 5MHZ-300MHZ 5SMD På lager: 75562 pcs RFQ</p>
<p>MACP-010561-000000 producenter: Aeroflex (MACOM Technology Solutions) Beskrivelse: RF DIR COUPLER 2GHZ-6GHZ 6TDFN På lager: 4788 pcs RFQ</p>	<p>MACP-010563-000000 producenter: Aeroflex (MACOM Technology Solutions) Beskrivelse: RF DIR COUPLER 10GHZ-30GHZ 6TDFN På lager: 6556 pcs RFQ</p>
<p>MACP-011010 producenter: Aeroflex (MACOM Technology Solutions) Beskrivelse: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD På lager: 69745 pcs RFQ</p>	<p>MACP-011014 producenter: Aeroflex (MACOM Technology Solutions) Beskrivelse: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD På lager: 34558 pcs RFQ</p>

